

2.11 TONS

TIME 6:56 AM
DATE 07/12/94
SUBTOTAL 4281 LB
TOTAL 4281 LB
WORLD RESOURCES CO.

6:56 AM 07/12/94
0 lb

WORLD RESOURCES COMPANY

8113 WEST SHERMAN STREET / PHOENIX, ARIZONA 85043 / (602) 233-9166


Mr. Gerald A. Thompson
Alaskan Copper Works
628 South Hanford Street
Seattle, Washington 98134

Dear Mr. Thompson:

Enclosed is the appropriate copy of the Uniform Hazardous Waste Manifest and the weigh ticket resulting from the transfer of the recyclable materials by your company to World Resources Company (WRC) and the transportation of these recyclable materials to the WRC Recycling Facility in Arizona for the purpose of recovering the metal values therein.

Sincerely,

WORLD RESOURCES COMPANY






Manifest Coordinator

Enclosures

Recycled Paper

AKC-0018285

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. W A D 9 8 0 7 3 8 5 4 6 9 4 0 0 4		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
		3. Generator's Name and Mailing Address ALASKAN COPPER WORKS 3200 Sixth Avenue South Seattle WA 98134		6. US EPA ID Number C A D 9 8 0 5 8 4 5 1 0		C. State Manifest Document Number		D. State Generator's ID	
4. Generator's Phone (206) 623-5801		5. Transporter 1 Company Name ALL WASTE INC.		8. US EPA ID Number		E. State Transporter's ID 421007		F. Transporter's Phone (602) 233-9871	
7. Transporter 2 Company Name		9. Designated Facility Name and Site Address World Resources Company 8113 West Sherman Street Phoenix, Arizona 85043		10. US EPA ID Number A Z D 9 8 0 7 3 5 5 0 0		G. State Facility's ID		H. Facility's Phone (602) 233-9166	
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers		13. Total Quantity		14. Unit Wt/Vol		1. Waste No.	
a. <div style="border: 1px solid black; padding: 2px;">HM</div> RQ, Hazardous waste, solid, n.o.s., (F006), 9, NA3077, III		No. Type		0 0 3 C F		0 4 4 5 7 P		F006	
b.									
c.									
d.									
J. Additional Descriptions for Materials Listed Above M35238						K. Handling Codes for Wastes Listed Above 01			
15. Special Handling Instructions and Additional Information 24 HOUR EMERGENCY RESPONSE: 1-(800) 424-9300 CHEMTREC (USE CHEMTREC COMPANY CODE "WORR") WEAR GOGGLES AND GLOVES									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name Gerald A. Thompson				Signature 		Month Day Year 10 7 08 9 4			
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature 		Month Day Year 10 7 08 9 4			
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Month Day Year			
Printed/Typed Name									
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name M. A. D. A. Z				Signature 		Month Day Year 10 7 1 2 9 4			

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. W.A.D.9.8.0.7.3.8.5.4.6.9.4.0.0.4	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ALASKAN COPPER WORKS 3200 Sixth Avenue South Seattle WA 98134				A. State Manifest Document Number		
4. Generator's Phone (206) 623-5801				B. State Generator's ID		
5. Transporter 1 Company Name				C. State Transporter's ID		
6. US EPA ID Number				D. Transporter's Phone 421007		
7. Transporter 2 Company Name				E. State Transporter's ID (602) 233-9871		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address World Resources Company 3113 West Sherman Street Phoenix, Arizona 85043				G. State Facility's ID		
10. US EPA ID Number				H. Facility's Phone (602) 233-9166		
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.	
a. HM		No.	Type			
b. RQ, Hazardous waste, solid, n.o.s., (F006), 9, NA3077, III		0.03	C.F.	0.4457	P	F006
c.						
d.						
J. Additional Descriptions for Materials Listed Above H35238				K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information 24 HOUR EMERGENCY RESPONSE: 1-(800) 424-9300 CHEMTREC (USE CHEMTREC COMPANY CODE "WORR") WEAR GOGGLES AND GLOVES						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name			Signature		Month Day Year	
Gerald A. Thompson			<i>[Signature]</i>		7 1 94	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature		Month Day Year	
Printed/Typed Name			Signature		Month Day Year	
Richard J. Jeff			<i>[Signature]</i>		7 1 94	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Month Day Year	
Printed/Typed Name			Signature		Month Day Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name			Signature		Month Day Year	



Material Safety Data Sheet

F006 Recyclable Material (Filter Cake)

Recycler's Facility Name and Site Address:

World Resources Company
8113 West Sherman Street
Phoenix, Arizona 85043
Tele: 1-602-233-9166 Fax: 602-936-9164

Issued: 8/7/90
Revised: 9/15/93 - DLS

Call CHEMTREC only in the event of
emergencies during shipping that
involve a spill, leak, fire, or accident
(all calls are recorded)

For Emergencies During Shipping in
the US or Canada, Day or Night,
Call: CHEMTREC 800-424-9300
(Use Chemtrec Company Code "WRR")
For calls from other countries call:
202-483-7616 Collect

Section 1

PRODUCT - MATERIAL IDENTIFICATION

Generic Name: Electroplating/Metal-Finishing Wastewater Treatment Sludge
Environmental Protection Agency (EPA) Waste Classification: F006
Chemical Family: Metallic (Hydroxide) Precipitates
Synonym: Non-ferrous Metal Hydroxide Filter Cake

DOT Shipping Name: RQ, Hazardous waste, solid, n.o.s., (F006)
DOT Hazard Class: 9 Packaging Group III
DOT Identification Number: NA 3077
DOT Emergency Response Guide 31 Applies

Section 2

HAZARDOUS INGREDIENTS

Ingredient:	CAS Number:	Content %:	ACGIH-TLV	Toxicology: (rat, oral)
Copper Hydroxide	20427-59-2	0-30	1.0 mg/m ³ (Dust)	LD-50 1,000 mg/kg
Nickel Hydroxide	12054-48-7	0-15	1.0 mg/m ³ (Dust)	LD-50 1,500 mg/kg
Calcium Hydroxide	1305-62-0	0-15	5.0 mg/m ³ (Dust)	LD-50 7,340 mg/kg
Diatomaceous Earth	68855-54-9	0-10	6.0 mg/m ³ (Dust)	LD-50 3,160 mg/kg

Section 3

PHYSICAL AND REACTIVITY DATA

Description: Solid, Clay-like Clumps,
Gray/Green to Brown,
Water Content 30-80%

Density: 64 to 90 lbs/cu/ft
Incompatible Reactivity: None Known
Vapor Pressure: Insignificant
Stability: Avoid contact with acids
Polymerization: Will not occur

Boiling Point: Above 2600°C
Melting Point: Above 1800°C
pH: 7.0 to 10.0
Odor: Nil

Specific Gravity: 1 to 1.4
Solubility: Insoluble in water

Section 4

FIRE AND EXPLOSION DATA

Flashpoint: Nonflammable
Special Firefighting Procedures: None
Product Decomposition: (Due to Fire or Explosion): None
Oxidation: Non-oxidizing
Explosive: Non-explosive

NFPA
Fire Diamond



Section 5

TOXICITY

Listed Carcinogen component: Nickel

Toxicology: See Sec. 2 (Nickel Hydroxide)

Route of Entry: Inhalation and Ingestion

Section 6

HEALTH EFFECTS AND FIRST AID

Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry. Induce vomiting (do not induce vomiting or give a liquid to an unconscious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term Effects: Chronic overexposure may affect the following target organs or body systems—blood, digestive, respiratory, lungs, liver, kidneys and skin.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage and metal-sensitive skin or skin lesions.

Section 7

PRECAUTIONS FOR SAFE HANDLING

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment be used by personnel who will come in contact with the material. The equipment should include eye protection, respirator and gloves.

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover from rain.

Spills: Cleaning procedures should not create excessive dust. Vacuum when possible. Package material and send to World Resources Company at above address.

Section 8

CONTROL MEASURES

Respiratory Protection: NIOSH-MSHA approved respirators as required.
Other Protective Equipment: Coveralls are recommended, but not required.

Eye Protection: Safety Glasses recommended.
Hand Protection: Gloves recommended.

Section 9

GENERATORS VERIFICATION

This MSDS is provided solely for informational purposes and no warranty or responsibility is extended even though reasonable precautions have been taken in the preparation of the data contained for this recyclable material. To the best of my knowledge this MSDS describes the recyclable material listed on the attached Manifest Number: 94004 Telephone: (206) 623-5880 Date: 7-8-94

Company Name and Address: Alaskan Copper Works 628 sixth ave. south
Seattle WA 98134

Signature:

AZF-WRC 9/93

AKC-0018288



Recyclable Material

US DOT Description	Container		Quantity	Unit	Waste No.
	No.	Type			
RQ, Hazardous waste, solid, n.o.s. (F006), 9, NA3077, III	3	CF	4457	lbs	F006
Total Quantity			4457		

Weighed

By: 

Verified

By: Susan L. Winter

MATERIAL IDENTIFICATION

DOT SHIPPING NAME: Hazardous Waste Solid N.O.S. (F006)
DOT HAZARD CLASS: Class 9
UN OR NA NUMBER: NA 3077

1990
EMERGENCY
RESPONSE
GUIDE

DOT EMERGENCY RESPONSE GUIDE 31

POTENTIAL HAZARDS

FIRE OR EXPLOSION

Some of these material may burn, but none of them ignites readily.

HEALTH HAZARDS

Contact may cause burns to skin and eyes.

Fire may produce irritating or poisonous gases.

Runoff from fire control or dilution water may cause pollution.

EMERGENCY ACTION

Keep unnecessary people away.

Isolate hazard area and deny entry.

Self-contained breathing apparatus (SCBA) and structural firefighters, s protective clothing will provide limited protection.

CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE.(Use Chemtrec Company Code "WORR") If water pollution occurs, notify the appropriate authorities.

FIRE

Small Fires: Dry chemical, CO2, Halon, water spray or standard foam.

Large fires: Water spray, fog or standard foam is recommended.

Move container from fire area if you can do it without risk.

Do not scatter spilled material with high-pressure water streams.

Dike fire control water for later disposal.

SPILL OR LEAK

Stop leak if you can do it without risk.

Small Dry Spills: With clean shovel place material into clean, dry container and cover, move containers from spill area.

Small spill: Take up with sand or other noncombustible absorbent material and place into containers for disposal.

Large Spills: Dike far ahead of liquid spill for later disposal.

Cover powder spill with plastic sheet or tarp to minimizing spreading.

FIRST AID

In case of contact with material, immediately flush eyes with running water for at least 15 minutes.

Wash skin with soap and water.

Remove and isolate contaminated clothing and shoes at the site.

NOTE: If this response guide is used as an attachment for shipping documents, enter shipping manifest number in block below.

WAD980738546 94004

(Shipping Manifest Number)

NOTICE

TO: World Resource Company
8112 West Sherman Street
Phoenix, Arizona 85043

From: Alaskan Copper Works
628 South Hanford Street
Seattle, Washington 98134


SUBJECT: Land Disposal Restriction Notice

Manifest Number: 94004

Date of Shipment: JULY 8, 1994

This shipment of material, which is being provided for recycling, is subject to the land disposal restrictions of 40 CFR, Part 268, Subpart D or the prohibitions specified in 268.32 or RCRA 3004(d). The applicable Land Disposal Restriction Information is provided in accordance with 40 CFR 268.7 and is shown below:

EPA Material Number	Regulated Constituent	Subcategory	Treatability Group	Treatment Standards	
				CFR Reference	Prohibition Level
F006	N/A	N/A	Nonwastewater	40 CFR 268.41 40 CFR 268.43	---

By: 
Gerald A. Thompson
Alaskan Copper Environmental Assistant